



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|---|
| Alert number | A12/1240/16 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Honda |
| Name | MSX, NSS |
| Type / number of model | Honda MSX125 , Honda NSS300/A FORZA |
| Batch number / Barcode | Honda MSX125 manufactured from 22.02.2013 - 24.09.2015, Honda NSS300/A FORZA manufactured from 22.02.2013 - 24.09.2015 |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorbikes. |
| Country of origin | Thailand |
| Alert submitted by | Poland |
| Risk type | Injuries |
| Risk | The fuel pump's cover made of composite may be deformed because of long-term contact with fuel. The deformation may cause a pump impeller to stop and damage pump's engine, consequently stopping the motorcycle engine with no possibility to start it. This defect can cause an accident. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Bulgaria, Croatia, Denmark, Finland, Greece, Ireland, Portugal, Slovakia, Slovenia, Sweden, United Kingdom |
| Images | No pictures are available |