

---

Alert number **[A12/00537/21](#)**

Product **Motorcycle**

---

Risk type **Injuries**

**Due to deviations during the heat treatment of the raw material, cracks may occur on the handlebar clamps. Consequently, these cracks could cause the handlebar clamp to break off together with the mounted clip-on handlebars, increasing the risk of an accident.**

Category **Motor vehicles**

Type **Consumer**

Description **Motorcycle**

Brand **KTM**

Name **RC 390 R**

EC-type approval/model **e1\*168/2013\*00016\*01**

Production dates **Model Year 2018**

Alert submitted by **Austria**

Is the product counterfeit? **No**

Country of origin **Austria**

Measures taken by economic operators **Recall of the product from end users  
Manufacturer**

Date of entry into force **31/03/2021**

Company recall code - **<https://www.ktm.com/de-de/service/Safety.html>**