



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0202/16
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Honda
Name	VT750CS Shadow,VT750C2B and VT750C2S
Type / number of model	SC50C, SC53B, SC53C
Batch number / Barcode	Model years: 2010, 2011, 2012, 2014, Model years: 2010, 2011, 2013, 2014, Model years: 2010, 2012, 2013, 2014
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Japan
Alert submitted by	Poland
Risk type	Injuries
Risk	As a result of improper mounting, the BAS (bank angle sensor) wire harness might bend and break due to continuous vibration during riding, causing an engine stall and steering problems for the rider.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Denmark, Finland, Germany, Greece, Ireland, Portugal, Slovenia, Sweden, The Netherlands, United Kingdom
Images	No pictures are available