



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0403/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	BMW
Name	R1200GS, R1200GS Adventure, HP2 Mega Moto, HP2 Enduro, R1200RT, R900RT, R1200R, R1200ST, R1200S, HP2 Sport
Type / number of model	Types: R12, RHP2, R12T, R1ST, R12S, K12S, K12R; Type-approvals: e1*2002/24*0199*, e1*2002/24*0254*, e1*2002/24*0228*, e1*2002/24*0230*, e1*2002/24*0284*, e1*2002/24*0217*, e1*2002/24*0234*, e1*2002/24*0217*
Batch number / Barcode	Vehicles manufactured between 4 December 2002 and 5 April 2011 are affected.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Germany
Alert submitted by	Germany
Risk type	Injuries
Risk	During servicing of brake discs or when wheels are changed, the bolts may be tightened with excessive tightening torque. Cracks may appear in the wheel flange as a result. The cracks may, in the worst-case scenario, lead to the bolts breaking.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	The Netherlands, Ireland, Croatia, United Kingdom, Iceland, Slovenia, Sweden, Bulgaria, Spain, Greece, Denmark, France, Finland, Portugal, Norway, Hungary
Images	No pictures are available