



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00127/21
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	YAMAHA
Name	FJR1300, MT-10, MT-09, NIKEN, TMAX, XT1200
Type / number of model	Type-approval numbers: e13*2002/24*0574, e13*168/2013*00001, e13*168/2013*00008, e13*168/2013*00286, e13*168/2013*00332, e13*168/2013*00047, e13*168/2013*00660, e13*2002/24*0653, e13*168/2013*00062, Types: RP23, RP28, RN45, RN57, RN58, SJ14, SJ18, DP04, DP07
Company recall code	
Production dates	The affected vehicles were manufactured between 2012 and 2020.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	Japan
Alert submitted by	Germany
Counterfeit *	<b>NO</b>
Risk type	Injuries
Technical defect	Due to oxidation, an electrical fault may occur in the brake-light switch that is fitted on the handlebar brake lever. This may lead to malfunctioning of the cruise control, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Poland, Romania
Images	No pictures are available