



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0754/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycles
Brand	Ducati
Name	1199 Panigale - S; 1199 Panigale - SL; 1299 Panigale - S
Type / number of model	Type: H8/00 Type key: ACB Type: H8/06 Type key: ACK Type: H9/03 Type key: ACS EC-Type approvals: e3*2002/24*0586 EC-type approvals: e3*2002/24*0586 EC type approvals: e49*2002/24*0001
Batch number / Barcode	The vehicles in question were manufactured between 2014 and 2015.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle.
Country of origin	Italy
Alert submitted by	Germany
Risk type	Injuries
Risk	Insufficient tightening torque on the suspension strut screw can result in the nut on the piston rod loosening, thereby impeding the absorbent effect. In the worst case, the driver can lose control of the vehicle.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	The Netherlands, France, Denmark, Ireland, United Kingdom, Sweden, Greece, Portugal
Images	No pictures are available