



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1441/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle tyre
Brand	Dunlop
Name	Trailmax Meridian
Type / number of model	170/60 ZR17 M/C 72W, 150/70 ZR18 M/C 70W, 150/70 R17 M/C 69V
Batch number / Barcode	DOT: DK8C 4K1M, DOT: DK2H 4E1M, DOT: DKLL 4P1M; includes all weeks from 2319 to 3519.
OECD Portal Category	77000000 - Automotive
Description	Dunlop Trailmax Meridian motorcycle tyres.
Country of origin	France
Alert submitted by	Luxembourg
Risk type	Injuries
Technical defect	The tyres may be affected by an open tread splice that can lead to a tread bulge or tread detachment affecting the operation of the motorcycle.
Risk	In case the tread detaches during high-speed operation, the motorcycle could be subject to vibration and the driver may lose control, increasing the risk of an accident.
Measures adopted by notifying country	Recall of the product from end users
Images	<p>The images show four different views of Dunlop Trailmax Meridian motorcycle tires. The top image shows the 'MERIDIAN' branding on the sidewall. The second image shows the tread pattern and specifications '170/60 ZR17 M/C 72W'. The third image shows specifications '150/70 ZR18 M/C 70W'. The bottom image shows specifications '150/70 R17 M/C 69V'.</p>