

Safety Gate Alerts

Alert number **A12/00287/21**

Product **Motorcycle**

Risk type **Injuries**

The side stand bracket may become loose. This could potentially cause a parked motorcycle to fall, causing injury

to the rider or to people in close proximity.

Category Motor vehicles

Type Consumer

Brand **Ducati**

Name XDiavel

EC-type approval/model **e49*168/2013*00009*00**; **e49*168/2013*00009*01**

Production dates Model years: 2016 - 2018

Company recall code CR206

Weekly report number Report-2021-9

Alert submitted by **Poland**

Is the product counterfeit? Unknown

Country of origin Italy

Measures taken by economic Recall of the product from end users

operators Manufacturer

05/03/2021 Page 1