

Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/00022/21
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Ducati
Name	Scrambler 1100
Type / number of model	e3*168/2013*00023*01; e49*168/2013*00039*01
Company recall code	CR201
Production dates	
OECD Portal Category	77000000 - Automotive
Description	Ducati Scrambler 1100, Model Years: 2018 - 2021.
Country of origin	Italy
Alert submitted by	Poland
Counterfeit *	UNKNOWN
Risk type	Fire
Technical defect	The exhaust valve cable could contact the main positive battery wire. This can result in an electrical short circuit, increasing the risk of fire. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Images	No pictures are available