



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/01866/20
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	YAMAHA
Name	NMAX125, X-MAX125, X-MAX300, X-MAX400, YZF-R3, MT-03, XSR700, TRACER 700, TENERE 700
Type / number of model	e13*168/2013*00067, e13*168/2013*00164 Types: SH13, SH08, RM11, RM14, RM30, DM07, DM08, SEE6, SH12, SE93, SEC7, RH12, RH07, e13*168/2013*00287, e13*168/2013*00043, e13*168/2013*00003, e13*168/2013*00024, e13*168/2013*00782, e13*168/2013*00648, e13*168/2013*00649, e13*168/2013*00284, e13*168/2013*00241, e13*2002/24*0747,
Company recall code	
Production dates	The affected vehicles were manufactured between 2013 and 2020.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	France
Alert submitted by	Germany
Counterfeit *	<b>NO</b>
Risk type	Injuries
Technical defect	The rear retro-reflector does not properly reflect the light coming from behind the vehicle. As a result, the vehicle would not be sufficiently visible for the following traffic, increasing the risk of an accident. /
Risk	
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Greece
Images	No pictures are available