



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1575/19
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	BMW
Name	K 1600 GT, K 1600 GTL, K 1600 B
Type / number of model	- EC-type approval number: e1*168/2013*00010, e1*168/2013*00011; - Types: K 1600 GT, K 1600 GTL (K48 (0F01/0F11/0F02/0F12)) K 1600 B (K61 (0F51/0F53)); - Model year: 2015-2019
Batch number / Barcode	The affected vehicles were manufactured between 22.09.2015 and 26.09.2019
OECD Portal Category	77000000 - Automotive
Description	Motorcycle under BMW Recall code: 00 00 23 23 00.
Country of origin	Germany
Alert submitted by	Portugal
Risk type	Injuries
Technical defect	The functional "shift fork / selector sleeve / gearwheel" group of the gearbox might become damaged.
Risk	Consequently, two gears might be engaged at the same time causing the rear wheel to be blocked, or the teeth of the gears sheared off, increasing the risk of accidents.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Germany, Ireland, Poland
Images	No pictures are available