



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|---|
| Alert number | A12/0175/16 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycles |
| Brand | YAMAHA |
| Name | XJR1300 |
| Type / number of model | Model: XJR1300 and XJR1300C |
| Batch number / Barcode | 2007-2015 model years are concerned. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Motorcycles. |
| Country of origin | Japan |
| Alert submitted by | Greece |
| Risk type | Injuries |
| Risk | Due to insufficient clearance between the chain and oil nozzle, the chain could come in contact with an oil nozzle. This may cause the tip of the oil nozzle to break and get stuck between the primary chain and gear, which may cause the vehicle to suddenly stop. |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Croatia, Denmark, Finland, Germany, Ireland, Norway, Portugal, Slovakia, Slovenia, The Netherlands, United Kingdom |
| Images | No pictures are available |