



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0646/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Yamaha
Name	YZF-R1M
Type / number of model	EC type approval: e13*2002/24*0740, Type: RN32
Batch number / Barcode	Unknown
OECD Portal Category	77000000 - Automotive
Description	The vehicles concerned are manufactured in 2015.
Country of origin	Japan
Alert submitted by	Germany
Risk type	Injuries
Risk	Due to insufficient tightening, the connecting rod nut for the shock absorber may become detached and thus impair the shock-absorbing effect. In the worst-case scenario the rider may lose control over the motorcycle.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	The Netherlands, Slovenia, Sweden, United Kingdom, Croatia, France, Denmark, Greece, Portugal, Norway
Images	No pictures are available