



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0875/16
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycles
Brand	Yamaha
Name	YZF-R3A and MT-03A
Type / number of model	Models YZF-R3A (B023/4/B/C) and MT-03A (B082/3)
Batch number / Barcode	2015-2016 model year.
OECD Portal Category	77000000 - Automotive
Description	Motorcycles.
Country of origin	Indonesia
Alert submitted by	Greece
Risk type	Injuries
Risk	The clutch pressure plate bearing may break when the clutch is operated frequently due to insufficient load rating of the bearing. As a consequence, the clutch may fail to operate and the transmission will not shift properly. There is a possibility that engine oil pressure may not regulate properly due to an improper design of the oil relief valve in the oil pump. As a consequence, the resin gear may break which could result in engine damage due to lack of oil supply.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Bulgaria, Croatia, Denmark, Finland, Germany, Ireland, Norway, Slovakia, Slovenia, Sweden, The Netherlands
Images	No pictures are available