



## Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/1265/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycle
Brand	Suzuki
Name	GSX-S1000
Type / number of model	FL6
Batch number / Barcode	Unknown
OECD Portal Category	77000000 - Automotive
Description	Motorcycle.
Country of origin	Japan
Alert submitted by	Hungary
Risk type	Burns
Risk	There is an insufficient margin of clearance between the radiator outlet hose and the exhaust pipe. As a consequence, it is possible that the radiator outlet hose might contact the exhaust pipe causing damage to the radiator outlet hose. In the worst case, this could lead to the leaking of engine coolant which could cause burns to the rider.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	Croatia, Slovenia, Slovakia, United Kingdom, Norway, Portugal
Images	No pictures are available